

SUPPLEMENTAL TYPE CERTIFICATE

10079703

This Certificate/Approval is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation and in accordance with Commission Regulation (EU) No. 748/2012 to

MT-PROPELLER ENTWICKLUNG GmbH

FLUGPLATZSTRASSE 1
94348 ATTING
GERMANY
EASA.21J.020

and certifies that the change in the type design for the product listed below with the limitations and conditions specified meets the applicable Type Certification Basis and, if applicable, environmental protection requirements when operated within the conditions and limitations specified below:

Type Certificate Number: US 3A15

Type Certificate Holder: TEXTRON AVIATION INC.

Type: Beechcraft 33,35,36 (Bonanza)

Model: 35-33, 35-A33

35-B33, 35-C33

E33, F33, H35, J35, K35, M35

Description of Design Change:

Installation of MTV-9-D/200-52() Propeller on Beechcraft ()33, ()35 and 35-()33 aircraft.

EASA Certification Basis:

The Type and OSD Certification Bases for the original product as amended by the following additional or alternative airworthiness requirements:


the following paragraph(s) at a later amendment: CS-36 Amdt 6, FAR 36 Amdt 36-31

This certificate/approval involves a change with an impact on the noise database and/or emission levels. The environmental protection requirements are amended as follows: CS-36 Amdt 6, FAR 36 Amdt 36-31

See Continuation Sheet(s)

For the European Union Aviation Safety Agency

Cologne, Germany, 12 July 2022



Marco CAPACCIO
Section Manager

Small Aircraft, Balloons & Airships



Associated Technical Documentation:

According to MT-Propeller Master Documentation List No. E-3776 Rev. 0

To be operated in accordance with MT-Propeller AFM-S Document No. E-3778 Rev. 0

To be installed i.a.w. MT-Propeller Installation Instruction Doc. No. E-3779 Rev. 0

To be maintained i.a.w. MT-Propeller ICA Doc. No. E-3780 Rev. 0

or later revisions of the above listed document(s) approved/accepted under the EASA system.

Limitations/Conditions:

According limitation section of AFM-S

Prior to installation of this change/repair it must be determined that the interrelationship between this change/repair and any other previously installed change and/ or repair will introduce no adverse effect upon the airworthiness of the product.

- End -