

# SUPPLEMENTAL TYPE CERTIFICATE

## 10076571

This Certificate/Approval is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation and in accordance with Commission Regulation (EU) No. 748/2012 to

# MT-PROPELLER ENTWICKLUNG GmbH

FLUGPLATZSTRASSE 1 94348 ATTING GERMANY

EASA.21J.020

and certifies that the change in the type design for the product listed below with the limitations and conditions specified meets the applicable Type Certification Basis and, if applicable, environmental protection requirements when operated within the conditions and limitations specified below:

Type Certificate Number: US 1A10

Type Certificate Holder: PIPER AIRCRAFT, INC.

Type: PA-23

Model: PA-23-235, PA-23-250

PA-E23-250

## Description of Design Change:

Installation of MTV-12-() propeller on Piper PA-23-235, PA-23-250 and PA-E23-250 aircraft.

### **EASA Certification Basis:**

The Certification Basis for the original product as amended by the following additional or alternative airworthiness requirements:

-The following paragraph(s) at a later amendment: CS 36 Amdt 5, FAR 36-31.

This certificate/approval involves a change with an impact on the noise database and/or emission levels. The environmental protection requirements are amended as follows: CS 36 Amdt 5.

See Continuation Sheet(s)

For the European Union Aviation Safety Agency

Cologne, Germany, 28 May 2021

Manfred REICHEL
Section Manager

Small Aircraft, Balloons & Airships Section



Task Number: 10053809

MT-PROPELLER ENTWICKLUNG GmbH - 302829



#### **Associated Technical Documentation:**

- According to MT-Propeller Master Documentation List No. E-3317 Rev. 0
- To be operated in accordance with MT-Propeller AFM-S Document No. E-3314 Rev. 0
- To be installed i.a.w. Installation Instruction Doc. No. E-3315 Rev. 0
- To be maintained i.a.w. MT-Propeller ICA Document No. E-3316 Rev. 0

or later revisions of the above listed document(s) approved/accepted under the EASA system.

#### Limitations/Conditions:

According limitation section of AFM-S.

Prior to installation of this change/repair it must be determined that the interrelationship between this change/repair and any other previously installed change and/ or repair will introduce no adverse effect upon the airworthiness of the product





Task Number: 10053809